



4161 Tamiami Trail, Suite 101, Port Charlotte, FL 33952-9204 www.flengineeringllc.com | Phone: (941) 391-5980

License Number #30782, #60102

May 14, 2025

121 Golden Condo Association

Re: 121 Golden Isles Dr.

Hallandale Beach, FL 33009 Re: PL-BSIP-24-01703

Folio #: 5142-26-BD-0020 through 0980

To: City of Hallandale Beach Attn: Building Official

This letter is to certify to the Owner of the subject property and the City of Hallandale Beach, that the subject building has been inspected as part of the building re-certification effort by a certified building inspector of Florida Engineering, and that the building is electrically safe for the specified use for continued occupancy in accordance with Broward County Board of Rules and Appeals Policy #05-05-111(G)(2).

"As a routine matter, in order to avoid possible misunderstanding, nothing in this letter should be construed directly or indirectly as a guarantee for any portion of the structure or electrical system. To the best of my knowledge and ability, this letter represents an accurate appraisal of the present condition of the existing building upon visual inspection and evaluation of observed conditions, to the extent reasonably possible."

Please let me know if you have any questions or concerns

Thank you,

Manuel Santiago, P.E.

License Numbers: 94979 (FL), 22016 (CA)

(941) 391-5980 manuel@fleng.com

ELECTRICAL SAFETY INSPECTION REPORT FORM

Inspection Firm or Individual Name: Florida Eng	ineering LLC
Address: 4161 Tamiami Trail. Port Charl	
Telephone Number: (941) 391-5980	PULES AND
Inspection Commenced Date: 4-28-2025	Inspection Completed Date: 4-28-2025
No Repairs Required Repairs	are Required as Outlined in the Attached Inspection Report
Florida Licensed Professional: Engineer	Architect
Name: Manuel Santaigo	
License Number: 94979	
	0
I am qualified to practice in the discipline in which I am	Seal hereby signing
ram qualified to practice in the discipline in which ram	
Signature:	_{Date:} 05/14/2025
	elines for building safety inspection as listed in the Broward County Board dge and ability, this report represents an accurate appraisal of the present erved conditions to the extent reasonably possible.
1. DESCRIPTION OF STRUCTURE	
a. Name on Title: 121 Golden Isles Drive Co	ndominium Association.
b. Street Address: 121 GOLDEN ISLES DRIV	/E, HALLANDALE BEACH FL 33009-5806
c. Legal Description: DORSEY ARMS CONDO UNIT	#### AKA 121 GOLDEN CONDO PER AMCDO CIN 112222083
d. Owner's Name: 121 Golden Isles Drive Co	
e. Owner's Mailing Address: 121 GOLDEN ISLES	ndominium Association.
	B DRIVE, HALLANDALE BEACH FL 33009-5806
f. Email Address: goldencondo@outlook.com	S DRIVE, HALLANDALE BEACH FL 33009-5806
f. Email Address: goldencondo@outlook.cor g. Folio Number of Property on which Building is Located: {	DRIVE, HALLANDALE BEACH FL 33009-5806 Contact Number: Luis Caamano 239-330-0289
•	S DRIVE, HALLANDALE BEACH FL 33009-5806 Contact Number: Luis Caamano 239-330-0289 5142-26-BD-####
g. Folio Number of Property on which Building is Located:	S DRIVE, HALLANDALE BEACH FL 33009-5806 Contact Number: Luis Caamano 239-330-0289 5142-26-BD-####
g. Folio Number of Property on which Building is Located: § h. Building Code Occupancy Classification: R2-RESID i. Present Use: R2-RESIDENTIAL	S DRIVE, HALLANDALE BEACH FL 33009-5806 Contact Number: Luis Caamano 239-330-0289 5142-26-BD-####

I. Special Features:
None
m. Additional Comments:
Main electrical room in Ground Floor. Additional rooms and meter stacks in 4th-6th-7th-8th-10th and
12th.
No Storage is allowed in electrical rooms.
2. INSPECTIONS
a. Date of Notice of Required Inspection: Unknown
04.00.0005
c. Name and Qualifications of Individual Preparing Report:
The electrical inspection was performed by Arthur Cantero. Arthur Cantero is an experienced general
contractor and professional engineer in the state of Florida with more than 30 years of experience in the construction, engineering and development industry. The report was reviewed by Manuel Santiago
as a professional engineer in the state of Florida with electrical knowledge and background for over 15
years.
d. Are any Electrical Repairs Required?
1. No − None Required
2. Yes – Required (Describe Nature of Repairs):
Too Required (Bessings Hattare of Repairs).
In Good Condition
*** NOTE: Provide photographs as necessary to reflect relevant conditions and index appropriately. ***
NOTE. I Tovide photographs as necessary to renect relevant conditions and much appropriately.
3. ELECTRIC SERVICE
400/040
a. Size: Voltage (<u>120/240</u>); Amperage (<u>4000</u>);
b. Main Service Protection (1500 Amps Amps): Fuse Breaker

c. Service Rating Amperage (100-125 Amps): d. Phase: Three Phase Single Phase e. Condition: Good Needs Repairs	Main Board 120/240V 4000 Amps Board #1 120/240V 225 Amps 3P-4W Board #2 120/240V 200 Amps 3P-4W Board #3 120/240V 100 Amps 3P-4W Board #1 Pumps Board #2 H1 Leg and Laundry Board #3 Elevator and Pumps		
Describe the Nature of Repairs: Main electrical room in good condition and well maintained. Individual meter stacks are in different accesory electrical rooms: Ground Floor units G1 to 307, 4th Floor units 401 to 507, 6th Floor units 601 to 707, 8th Floor units 801 to 907, 10th Floor units 1001 to 1107, 12th Floor units 1201 to PH7-RGN-RGS. All in good condition.			
4. SERVICE EQUIPMENT			
a. Clearances: Good Requires Repair Describe the Nature of Repairs: In good condition.			
5. ELECTRIC ROOMS			

6 GUTTI	FRS WIRI	EWAYS, ETC.			
0. 00111	LING, WIIN				
a.	Location:	Good F	Requires Repair		
Describe t	the Nature c	of Repairs:			
	condition				
iii good	Condition				
b.	Taps and B	ox Fill: Good	Requires Repa	air	
	the Nature c				
In good	condition	1.			
7. ELEC	TRICAL S	WITCHGEAR			
				1 1	
a.	Panel #	(House 1)	Good	Needs Repairs	
h	Panel #	(House 2	√ Good	Needs Repairs	
b.	Fallel#	(1.0000)	V		
c.	Panel #	(House 3)	Good	Needs Repairs	
		_	√ Good	Needs Repairs	
d.	Panel #	(Generator)	▼ G000	Needs Repairs	
e.	Panel #	(Elev 1 and 2	Good	Needs Repairs	
	i diloi ;;	/			
Describe t	the Nature c	of Repairs:			
f. Panel	# (Laund	dry Room) Condition: (Good		

8. BRANCH CIRCUITS
a. Identified: b. Conductors: Yes Good Deteriorated Must Be Identified Must Be Replaced Describe the Nature of Repairs: In good condition.
in good condition.
9. GROUNDING OF SERVICE
Good Repairs Required Comments: In good condition.
10. GROUNDING OF EQUIPMENT
Good Repairs Required
Comments: In good condition.

11. SERVICE CONDUITS/RACEWAYS
Good Repairs Required
Comments:
In good condition.
12. SERVICE CONDUCTOR AND CABLES
Good Repairs Required
Comments:
In good condition.
13. GENERAL CONDUIT/RACEWAYS
Good Repairs Required
Comments:
In good condition.

14. FEEDER CONDUCTORS
Good Repairs Required
Comments:
In good condition.
15. BUSWAYS
a. Location: Good Repairs Required
Describe the Nature of Repairs:
N/A
16. OTHER CONDUCTORS
Good Repairs Required
Comments:
In good condition.
17. EMERGENCY LIGHTING
Good Repairs Required
Comments:
In good condition.

18. BUILDING EGRESS ILLUMINATION
Good Repairs Required
Comments:
In good condition.
19. FIRE ALARM SYSTEM
Good Repairs Required
Comments:
N/A
20. SMOKE DETECTORS
20. SMOKE DETECTORS Good Repairs Required
Good Repairs Required
Good Repairs Required Comments:
Good Repairs Required Comments: N/A
Comments: N/A 21. EXIT LIGHTS
Good Repairs Required Comments: N/A 21. EXIT LIGHTS Good Repairs Required
Good Repairs Required Comments: N/A 21. EXIT LIGHTS Good Repairs Required Comments:
Good Repairs Required Comments: N/A 21. EXIT LIGHTS Good Repairs Required Comments:

22. EMERGENCY POWER SYSTEMS
Good Repairs Required
Comments:
Emergency generator: Will service emergency light systems and one elevator. It is located in a
mechanical room in the garage. In good condition and well maintaned.
23. WIRING AND CONDUIT AT ALL PARKING LOTS AND GARAGES
Good Repairs Required
Comments:
In Good Condition
24. SWIMMING POOL WIRING
Good Repairs Required
Comments:
N/A
25. WIRING TO MECHANICAL EQUIPMENT
Good Repairs Required
Comments:
Comments:

121 GOLDEN ISLES DRIVE, HALLANDALE BEACH FL 33009-GOLDEN ISLES CONDOMINIUM ASSOCIATION, INC.

ELECTRICAL, MECHANICAL AND LIFE SAFETY REPORT:



Image 3: Pump room.

Image 4: Pump room.