



Inspection Photos
121 Golden Isles Drive



Front



Back



Left




Right

This insurance inspection is limited in scope and was conducted solely to assist the policyholder to obtain property insurance via a licensed insurance agent, and it may not be used for any other purpose. Thank you for using DMI. For comments, questions, or to request an inspection please contact Don Meyer Inspections at (800) 469-0434 or at info@windstorminspections.com



Inspection Photos
121 Golden Isles Drive



Reinforced Concrete Roof Deck



Impact Rated Windows



Impact Rated Window Etching/Engraving




Impact Rated Glazed Door

This insurance inspection is limited in scope and was conducted solely to assist the policyholder to obtain property insurance via a licensed insurance agent, and it may not be used for any other purpose. Thank you for using DMI. For comments, questions, or to request an inspection please contact Don Meyer Inspections at (800) 469-0434 or at info@windstorminspections.com




Inspection Photos
121 Golden Isles Drive




Impact Rated Glazed Door Etching/Engraving



Impact Rated Glazed Door



Impact Rated Glazed Door Etching/Engraving



Unprotected Glazed Entry Door (Common Area)

This insurance inspection is limited in scope and was conducted solely to assist the policyholder to obtain property insurance via a licensed insurance agent, and it may not be used for any other purpose. Thank you for using DMI. For comments, questions, or to request an inspection please contact Don Meyer Inspections at (800) 469-0434 or at info@windstorminspections.com



Inspection Photos
121 Golden Isles Drive



Address



Built-Up Tar & Gravel Roof Covering



Built-Up Tar & Gravel Roof Covering